



Crawler unit may vary



Pipe Inspection Diameter: from 100mm up to 1250mm

Our CCTV surveys are proven and well established in finding faults in your sewage and drainage system. Our high tech CCTV equipment can allow the user to view real time images and videos of the affected pipe with full colour pan, this is also twinned with a rotating camera with leg lights to spot the damaged or blocked pipe section.

Typical faults found in sewage systems

- Fractures to the pipe structure
- Infiltration
- Grease build up
- Silt build up
- Root infestation
- Broken pipe
- Displaced joints
- Builders rubble
- Open joints

Reports

We generate reports within the international sewer coding standards (OS20X). We can also provide optional extras in the reports including still images of the problem area, detailed map giving location of sewer and video of the survey on a DVD or can be send in Mpeg format.



CCTVCCU- APR 2017